

QuestSpecialty

**FREZE-IT**

**Chewing Gum  
Remover**

**FREZE-IT**

**Chewing Gum Remover**  
**Removedor de Goma de Mascar**

**Freezes Gum & Candle  
Wax for Easy Removal**

**ENVIRONMENTALLY SAFE-WILL NOT HARM THE ATMOSPHERE**

**DANGER/PELIGRO:**

**EXTREMELY FLAMMABLE AEROSOL. CONTAINS GAS  
UNDER PRESSURE; MAY EXPLODE IF HEATED.**  
**AEROSOL EXTREMADAMENTE INFLAMABLE. CONTIENE  
GAS A PRESIÓN; PUEDE EXPLOTAR SI SE CALIENTA.**

**NET WT. 7 OZ. (198 g)**

QuestSpecialty Corporation  
P.O. Box 624 • Brenham, TX 77834  
713.896.8188

*FREZE-IT is a unique freezing agent for fast easy removal of gum and wax deposits from carpet, upholstery, floors, furniture, walls, staircases and chairs. Quickly removes tackiness from gum and wax without harming, staining or marking painted surfaces. This product has been authorized by the USDA for use in federally inspected meat and poultry plants.*

**DIRECTIONS FOR USE:** Remove cap and spray product on chewing gum or wax deposit for 20 to 30 seconds. Remove deposit by scraping with a spatula, spoon or knife. If initial application does not remove all the deposit, re-apply.

**MODO DE EMPLEO:** Remueva la tapa y rocíe la goma de mascar o depósito de cera por 20 o 30 segundos. Remueva los depósitos tallando con una espátula, cuchara o cuchillo. Si la primera aplicación no remueve todos los depósitos, vuelva a aplicar.


**DANGER:** Extremely Flammable Aerosol. Contains gas under pressure; may explode if heated. Keep away from heat, sparks, open flames, and hot surfaces. —No smoking. Do not spray on an open flame or other ignition source. Pressurized container: Do not pierce or burn, even after use. Protect from sunlight. Do not expose to temperatures exceeding 50°C/122°F. Store in a well-ventilated place.

**PELIGRO:** Aerosol Extremadamente Inflamable. Contiene gas a presión; Puede explotar si se calienta.

Mantenga lejos de calor, chispas, llamas abiertas, y superficies calientes. —No fumar. No pulverice en llamas abiertas u otra fuente de ignición. Envase presurizado: No perforé ni queme, incluso después de usar. Proteja de la luz solar. No exponga a temperaturas que excedan 50°C/122°F. Almacene en un lugar bien-ventilada.

**CONTAINS (CAS#):** Propane/n-Butane (68476-86-8).

|              |   |
|--------------|---|
| HEALTH       | 1 |
| FLAMMABILITY | 4 |
| REACTIVITY   | 0 |
| PERSONAL     | A |



ITEM 2280

Made in USA



600005228